

RS SWITCH ROUTER RapidOS Documentation Errata Sheet

Version 9.3

This document describes all of the changes that have been made to the documentation since release.

The following table lists the changes made, what documents were affected, and the date that the changes were implemented.

Date	Document Changed	Chapter	Page #	Description of Change	Document Revision
3/9/03	CLI Reference	IPX - 37		Lack of support for IPX in RapidOS is documented	0B
3/9/03	User Guide	multiple		Due to lack of support for IPX in RapidOS, the IPX configuration chapter is removed as well as all references to any IPX routing capacity.	0B
4/10/04	All Getting Started Guides	Introduction and Hardware Installation		A Warning was added for both AC and DC power supplies describing the need for proper earth grounding of power supplies. It makes clear that not grounding of the equipment can lead to equipment failure and voiding of the warranty.	0B